

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/Ala Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014491**Date Inspected:** 14-Apr-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower and OBG Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector George Goulet was present during the times noted above for observations relative to the work being performed.

OBG Assembly Yard

This QA Inspector proceeded to the OBG Assembly Yard in response to ZPMC Inspection Notification # 005523 for magnetic particle testing (MT) of the following:

This QA Inspector performed random visual testing and then MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member is identified as OBG Segment 9DE.

The weld designations reviewed and identified as Tag 3 were:

SEG056B-001, 022, 052

SEG056C-022, 024, 052

The weld designations reviewed and identified as Tag 4 were:

SSD23-PP79.5-041, 042, 043, 044, 051, 052, 081, 082, 083, 084, 089, 090, 091, 092, 093, 094

SSD16A-PP080-040, 042, 044, 096, 098, 100, 221, 233, 237, 241, 253, 255, 257

SSD16-PP080-010, 027, 029, 031, 035, 037, 039, 041, 083, 085, 087, 221, 228, 235, 237, 239, 241, 253, 255, 257, 259

SSD24-PP80.5-041, 042, 043, 044, 075, 076, 077, 078, 079, 080, 081, 082, 083, 084, 087, 088, 089, 090, 091, 092,

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

The weld designations reviewed and identified as Tag 5 were:

SEG056G-005, 006, 007, 008

Tag 6

CA066-014, 018

CSD2-PP79.5-046, 052, 054, 062, 064, 076, 078

CSD2-PP80.5-046, 052, 054, 062, 064, 076, 078

SSD23-PP79.5-125, 129, 131, 139, 143, 151, 159, 161

CSD4-PP080-068, 072, 082, 090, 092, 101, 103, 111, 113, 119, 121, 140, 142

SSD16-PP80-136, 147, 149

SSD24-126, 132, 134, 150, 152, 160, 162

No apparent indications were observed.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No significant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet,George	Quality Assurance Inspector
----------------------	---------------	-----------------------------

Reviewed By:	Dawson,Paul	QA Reviewer
---------------------	-------------	-------------